



## L200 RPM conversion sheet

*Please note the display of the L200 centrifuge is set to show RPM (revolutions per minute).  
For conversion from / to G-force (RCF), please refer to the table below.*

RPM TO G-FORCE (RCF)	
RPM	G-Force (RCF)
1600	276
1700	312
1800	350
1900	389
2000	432
2100	476
2200	522
2300	571
2400	621
2500	674
2600	729
2700	786
2800	846
2900	907
3000	971
3100	1037
3200	1105
3300	1175
3400	1247
3500	1322
3600	1398
3700	1477
3800	1558
3900	1641
4000	1726
4100	1813
4200	1903
4300	1995
4400	2089
4500	2185
4600	2283
4700	2383
4800	2486
4900	2590
5000	2697
5100	2806
5200	2917
5300	3030

G-FORCE (RCF) to RPM	
G-Force (RCF)	RPM
276	1600
300	1668
400	1926
500	2153
600	2358
700	2547
800	2723
900	2888
1000	3045
1100	3193
1200	3335
1300	3471
1400	3602
1500	3729
1600	3851
1700	3970
1800	4085
1900	4197
2000	4306
2100	4412
2200	4516
2300	4617
2400	4717
2500	4814
2600	4909
2700	5003
2800	5095
2900	5185
3000	5273
3030	5300

